OXC-0823

Copy

19 August 1960

25X1A

MEMORANDUM FOR : The Record

SUBJECT

: OXCART Support in Development Projects Division

The following personnel have been designated by Branches or Sections as primary contacts in OXCART support matters:

Security

COVER

Personnel.

Operations

Construction

Development Branch

Changra

Engines

Air Frame and Related Systems

Elint and Communications

Communications



Administration, Contracts, Finance, Materiel, and Technical Analysis Chiefs furnish support on an on-call basis.

> JOHN PARANGOSKY Deputy Chief, Development Branch DPD-DD/P

DC/DB/DPD/JPAHANGOSKY:mjw Distribution: 0 & 1 - DC/DB/DPD

1 - A/CH/DPD

DOCUMENT NO. _ NO CHANGE IN GLASS. XT OEGLASSIFIED

Approved For Release 2001/07/27 CA-RDP81B00879R001000030006-6: TS S C 2012 AUTH: HR 70-2

DATE: 5/2/82 REVIEWER, 06/5/0

Approved For Release 2001/07/27: CIA-RDP81B00879R001000030006-6

Comy 7 of 7

19 August 1960

REPORTED IN THE PROCESS.

SUBJECT : Storage and Handling - PAI 523 Poel For JULID-304 English

25X1A

990 (Di **30**870)

L. As outlined in reference message, engine contractor testing reveals that thereal stability of subject fuel is adversely affected by contact with copper and/or silver. The magnitude of this effect is a function of and increases with copper/allver concentration, residence time, and temperature. Thereal stability therefore can be destroyed over long periods of time with very alight concentrations of copper or silver.

2. Special precautions will be required in the area of storage and handling tankage facilities and in the periodic classing of these facilities so that the use of cleaning equipment such as copper wire brushes is probibited.

SIGNED

25X1A Development Brench DELID/F

intribution: L-URI/DE 3-0/03/010 45-080/Seloriel 5-079/63 7-080/AI

rew (19 August 1960) NO SHANGE IN CLASS. DESLASSIFIED CLASS, ENGAGED TO: TS S C 20/2 ADIN: ME 10-2 5.11. 5/2/52 REVIEWER: 064540

25X1A